



2. INSPECT ENDCAP BORE FOR WEAR OR PITTING. BORE SHOULD BE SMOOTH AND TO SIZE SHOWN.



CAP ROTOR AND PUT MASKING TAPE OVER ALL BUT ONE VENT HOLE. APPLY AIR PRESSURE. BRUSH SOAP WATER SOLUTION OR BUBBLE SOAP TO VENT HOLE. ROTATE UNION BY HAND; IF NO BUBBLE RISES, UNION IS O.K.




TEST UNION WITH 100 PSI AIR PRESSURE BEFORE PERMANENT INSTALLATION.


TESTING

ASSEMBLY

NOTE: WHEN ASSEMBLING DEUBLIN UNIONS, CLEANLINESS IS AN IMPORTANT FACTOR. ALL PARTS MUST BE FREE OF DIRT AND CHIPS. THE PARTS MAY BE CLEANED WITH CARBON TETRA—CHLORIDE, DENATURED ALCOHOL, OR ANY GOOD CLEANING SOLVENT.


3. ASSEMBLE ENDCAP TO HOUSING WITH CAP SCREWS AS SHOWN.





REPAIR KIT 73010-000C.

2. ASSEMBLE NEW BACKUP WASHER AND O-RING ONTO FLOATING SEAL ASSY. PLACE (4) NEW SPRINGS INTO HOLES IN ENDCAP. ALIGN FLOATING SEAL WITH KEY PINS AND PUSH INTO BORE.



			'													
İ	6	972-610	COIL SPRING ASSOCIATED #C0180-026-0310	4	STAINLESS STEEL	T			EQUIPMENT REF:	SCALE					DEUB	IIN
- 1	-		"			-				DRM	LG 0	5/06/98		 -	-	
	כ	500-015	0-RING 120	1	BUNA-N 80 DUROMETER					ENGR	LG 0	5/06/98] }	$oldsymbol{oldsymbol{arphi}}$	WAUKEGAN	, ILLINOIS
	4	972-608	BACK-UP WASHER	1	TEFLON					APPO			TITLE:	REPAI	R INSTR	UCTION
	3	972-606	FLOATING SEAL ASSY	1	S/S CARRIER, SIC SEAL				ASSY/TEST FIXTURES REQUIRED:	UNI	ESS OTH	FRWISE		FOR	DEUBLIN	1 UNIO
	2	972-604	SEAL ASSY	1	ST. STL CARRIER/SIC SEAL	_			INEQUINED:	TOLE	ESS OTHE SPECIFIE RANCES	ED ±.010.	N	10DEL	73010-	-000-
ı	1	1300-016	0-RING 022	1	BUNA-N	┪	WAS 972-600C AND 972-600	02/03 RM	\exists		ENSIONS IN MILLIN		NO.		DA-6	. CA
ı	NO	PART NUMBER	DESCRIPTION	QTY	MATERIAL	LE		DATE SIGN	-	ARE	IN MILLIN	METERS.			DA-C	,9

COMPANY NOIS, U.S.A. ONS

IION (A))—101[~] C.A.D DRAW